






6/6

FIG. 6



(FORMATION OF COLUMN AND WALL MEMBERS BY PATTERNING)



(INJECTION OF LIQUID CRYSTAL)